





Utfärdare/Owner

Datum/Date 2015-02-19

Sida/Page

Test report summary

Strong Fix 2000 joules ST30

Report No. TR-15-006

Date: 2015-01-23

Place: Troax Test Center

Purpose

To document the effect of a very high energy impact test from inside the hazard zone with Strong Fix machine guard system, the 80x80 post and the ST30 x1000 mm wide mesh panel.

Test material

Panel: ST30 2050x1000 mm Post: Standard post 80x80 Fixing: Strong Fix bracket

Floor fixing: Bolted to the test rig

Test procedure

The test was performed in accordance with the pendulum test method stated in ISO 14120:2015 Annex C. Panels and posts were assembled with the Strong Fix system and fastened to the test rig with M12 bolts. The pendulum of 100 kg was adjusted so the impact hit the panel at 1446 mm above the floor, i e 1316 mm from the bottom of the panel (with a 150 mm floor gap). To reach the energy of 2000 J the 100 kg pendulum was raised 2036 mm from the starting point.

Impact energy

Pendulum mass: 100 kg Pendulum speed: 23 km/h

$$E = \frac{mv^2}{2} = \frac{100\left(\frac{23}{3.6}\right)^2}{2} = 2041 J$$

E = mgh = 100 * 9.82 * 2.036 = 2000 J

Results

The Strong Fix wall withstands the very high energy impact. The centre panel absorb all energy and obtain a remaining deformation with a total deflection of approximately 215 mm. The posts remain intact without noticeable deformation. Despite the very high energy impact there were no penetration and no parts departed.

Ola Eriksson

R&D Manager Troax AB

Josephine Granell

Product Manager A&R

Sweden